




TEFLON O-RING  
P/N P11015-219  
REPLACES P/N 12-6227T024  
QTY: 1




GASKET  
P/N 11-5028N000  
REPLACES P/N 10-450-28  
QTY: 1




RETAINING RING  
P/N P10202-100  
REPLACES P/N 12-R100S000  
QTY: 1




O-RING  
P/N P11000-219  
REPLACES P/N 12-6227N024  
QTY: 1




TEFLON BACK LIP  
P/N P11227-219  
REPLACES P/N 12-8774T024  
QTY: 2




RETAINING RING  
P/N P10202-068  
REPLACES P/N 12-R068S000  
QTY: 1



O-RING 90 SHORE  
P/N P11003-210  
REPLACES P/N 12-6227N015S  
QTY: 1



O-RING 90 SHORE  
P/N P11003-112  
REPLACES P/N 12-6227N010S  
QTY: 1



PISTON BUMPER  
P/N 11-5051P000  
REPLACES P/N 10-450-51  
QTY: 1



HELICAL SPRING LOCK WASHER  
P/N P10212-025  
REPLACES P/N 12-5001C407  
QTY: 1

1. COMPONENT PICTURES ARE FULL SCALE  
DO NOT REDUCE OR ENLARGE WHEN MAKING COPIES OF THIS DOCUMENT



SC HYDRAULIC ENGINEERING CORPORATION  
BREA, CA 92821

HYDRAULIC REPAIR KIT P/N 11-6099N015A  
REPLACES HYDRAULIC REPAIR KIT P/N 10-550-99-1.50A